

<b>PROJECTS</b>	<b>VALUE</b>	<b>COMMENTS</b>
Hurricane cleanup	\$64,950.00	Remove trees, shrubs, weeds, etc
New roof rectory	\$48,000.00	Installed before IAN damaged it
New Carillon Bells	\$16,700.00	Upgrade from existing out of date system
New fire hydrant	\$10,800.00	Identified during Fire Safety Inspection
AC Repairs	\$8,625.00	Various AC units and thermostats on campus
Rebuild backflow	\$4,900.00	Identified during Fire Safety Inspection
Purchase & install 7 radio dialers for fire and security monitoring	\$3,900.00	Upgrade from analog dialers to radio dial system
Repair Hall entry locks	\$3,600.00	Previous locks were not functioning and required replacement
SKD entry sign	\$3,400.00	Cleanup, repair, re-letter, paint and illuminate
Repair below grade at rectory	\$3,000.00	Section of rectory front wall was allowing seepage into the house
Replace water damaged flooring - rectory	\$2,600.00	See above
Repair broken sewer line	\$3,000.00	North side of campus near church was flowing freely, required repair
New blinds for Rectory	\$2,600.00	Master Bedroom were not damaged by IAN but when Family Room blinds were replaced due to IAN, the MBR blinds were ordered to match
Upgrade lights in church	\$1,965.00	Back walls of church lights were refitted with LED replacing fluorescent
Replace office flooring	\$1,300.00	Post IAN, some flooring was damaged, this was for flooring not damaged by needed replacement
Replace lights in office	\$1,000.00	Same upgrade as performed in the church
Repair rectory pool piping	\$700.00	Old valves were not working and new piping was required to replace the valves.
<b>UPCOMING PROJECTS</b>		
Repaving backroad	\$70,000.00	
Install sump pumps on church	TBD	Originally noted after IRMA, trying for Insurance to pay
Install lights in Hall		bulbs donated, need to install
Replace office analog cameras to digital	\$5,750.00	
Church sound system upgrades	Out for Quote	